

HARPER COUNTY ROAD & BRIDGE
Weekly County Commission Report
February 1-5, 2016

KENT STONEBRAKER-EAST FOREMAN

1. Dozer 627 pushing up sand at the Robb-Wedman Pit. Trucks 217, 305 & 606 hauling shale to Rd 733-J & intersection of 739&670. Graders patrolling.
2. Reset damaged commercial truck sign on Rd 706-30. Helped with CDL training. Graders patrolling.
3. Dozer 627 pushing up sand at the Robb-Wedman Pit. Trucks 217, 305 & 606 hauling sand to Rd's 673-17, 676-18, 676-19 & 737-I. Employee to Derby to take CDL written test. Graders patrolling.
4. Dozer 627 pushing up sand at the Robb-Wedman Pit. Graders patrolling. Trucks 217, 305 & 606 hauling sand to Rd's 672-13, 733-E, 670-14, 737-E & 755-H.
5. Trucks 305, 310 & 606 hauling sand to Rd's 678-29 & 767-I. Dozer 627 pushing up sand at the Robb-Wedman Pit. Graders patrolling.

JIM THOMPSON-SHOP FOREMAN

1. #120 2015 International Truck, service job-20,195 miles. #118 2006 Sterling Truck, checked out electrical wiring problems. #361 CAT 120M, service call-sos engine samples.
2. #124 2015 International, service job-20,199 miles.
3. Cleaned shop waste oil heater. Appraiser 2008 Chevrolet, service job-193,522 miles.
4. DOA 2011 Dodge, service job-154,206 hours. #155 JD 670G, service job-666 hours.
5. Cleaned shop.

LAWRENCE SMITH-WEST FOREMAN

Excavator 632 removing trees on Rd 729-D with permission to place on landowner, reset fence. Excavator 632 knocking down limbs & trees on Rd 731-B & placed in ditch. Dozer 628 pushing up & stockpiling sand at Burnet & Jones Pits. Sanded Rd's 700-8 & 9, 727-V & X, 706-3, 719-O & P, 721-R & S, 723-M & 719-Q. Reset signs on Rd's 735-AA, 725-A & B, 739-V, 717-A, 662-7, 719-N & 679-7.

JEFF NULIK-BRIDGE FOREMAN

1. Made repairs at Bridge 674-9 #1. Checked needed repairs at Bridges 674-3, 680-3, 676-4, 686-14 & 727-J. Completed repairs at Bridge 735-N.
2. Checked Bridge's 757-F & 696-6 for needed repairs. Helped with plates at Bridge 674-9 #1. Tire repair to 682. Attended One Call training at Medicine Lodge.
3. Measured for sheet piling at Bridge 676-4. Serviced 611. Moved grader blades at Attica & Harper.
4. To Anderson Welding for supplies. Checked needed repairs at Bridge's 711-R, 709-V, 729-X, 706-12 & 694-17.
5. Checked needed repairs at Bridge's 706-12, 709-X & 709-F.